From: Moore, Gary
To: Omar Valdez

Subject: CES Impact to Residential Properties/ROWs (1 of 2 emails)

Date: Friday, August 08, 2014 11:58:25 AM

Attachments: <u>IMG 0392.JPG</u>

IMG 0393.JPG IMG 0394.JPG IMG 0395.JPG

Omar:

See Pictures.

The pictures form 8/2/14 pictures are after the COH actions on 8/1/14 and before OMI (TCEQ Contractor) started their cleanup.

The pictures from 8/8/14 are from after demobe. TCEQ flushed all ditches and stained areas with fresh water and may have used some microblaze on the stained areas and sucked up all the water in the ditches. EPA ended up weedeating the stained grass and collected the clipping but you can still see the staining.

Thanks **Gary Moore**

Federal On-Scene Coordinator U.S. EPA Region 6 214-789-1627 cell 214-665-6609 office moore.gary@epa.gov







